INDUSTRIAL ENGINEERING

PLANT ENGINEERING IN INDUSTRY

A McGRAW-HILL PUBLICATION

Copyright 1930

INDEX TO VOLUME 87

January to December, 1929

PAGES BY MONTHS

January	1 to 56
February	57 to 108
March	109 to 176
April	177 to 224
May	225 to 272
June	273 to 338
July	339 to 388
August	389 to 432
September	433 to 488
October	489 to 554
November	555 to 602
December	603 to 660

A

Acetylene welding (see Welding).
Air conditioning (see Ventilation).
Alarm (see Signals).
Announcements (also see Meetings forthcoming).
——A. I. E. E. offers diversified program for summer convention, 286.
——Are you ready for the question? (editorial comment), 245.
——Belting leather industry to convene on business practice, 560.
——Chicago electrical maintenance men hold dinner, 108.
——Coming—a golden jubilee of light (editorial comment), 244.
——Cutler-Hammer companies change name, 108.
——Equipment show, See you at Pittsburgh? (editorial comment), 244.
——Fourth midwest conference and power show, 93.
——Heating and ventilating exposition, First international, 539.
——Industrial truck association now organized, 108.
——Light's golden jubilee, 466.
——McGraw-Hill to publish "Aviation," 184.
——Modernization October issue, 463.
——Modernization the theme of October issue, 350.
——National electrical exposition to be held in New York, 378.
——National electric exposition, 466.
——National industrial exposition, 508.
——New equipment review in January, 1930, issue, 525.
——Power show, Eighth national, 508.
——Radio "salutes" to industry, 608.
——Third regional meeting held by P. T. A., 148.
——We have moved to Chicago (editorial comment), 57.
——(Westinghouse Lighting Institute) Men responsible for illumination will welcome permanent lighting exhibit (editorial comment), 244.
——Westinghouse opens light exhibit, 332.
Arc welding (see Welding).
Are you ready for the question?
——(editorial comment), 245.
——let's sweeten the pot (editorial comment), 225.
——Should the plant engineering department have the right to question orders? 354.
Discussion: (H. L. Schultz) 399, (H. E. Stafford) 400, (Maurice C. Cockshott) 401, (L. B. Coon) 452, (Elmer Housley) 452, (H. W. Benton) 592, (R. H. Kasper) 634.
——Who shall do the cleaning? 398.
Discussion: (M. B. Kramer) 451, (Marin Phillips) 451, (Marin Phillips) 591, (George S. Billman) 591, (J. C. Looser) 592, (H. E. Stafford) 633, (Maurice Peterson) 634.
——What shall be the maintenance policy? 226.
Discussion: (T. A. Keefer) 355, (Robert W. Drake) 356, (Maurice C. Cockshott) 356, (Walter C. George) 357, (George S. Billman) 401, (W. H. Pendergrass, Sr.) 401, (H. M. Benton) 453, (H. E. Stafford) 454, (C. C. Wilcox) 455, (H. D. Fisher) 456, (K. D. Hamilton) 457.
——Who shall do the oiling? 589.
Discussion: (Elmer Housley) 630, (Herbert L. Schultz) 630, (M. B. Kramer) 630, (Marin Phillips) 630.
——Who should do the salvaging? 629.
Discussion:
——Who shall do the welding? 450.
Discussion: (A. E. Windle) 590, (M. Peterson) 591, (Harry W. Benton) 632, (H. D. Fisher) 633, (M. C. Cockshott) 633.
Armatures (see Motor coils, Motor winding and Motor reconnection and repair).
Around the works, *11, *97, *168, *210, *263, *364, *410, *586, *638.

B

Batteries:
——Charging equipment for electric trucks and tractors, battery (H. M. Martin), *191.
——Charging room for plant trucks, battery (Chas. A. Peterson), *211.
——Reducing cost of operating siren (Frank Gillooly), 82.
——Trucks and tractors, When to replace storage battery, *158.
Bearings:
——Anti-friction bearings, When to replace, *138.
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Cement, Offsetting wear and tear on equipment in making, *281.
——Currents caused by solenoid shaft osillator, Bearing (W. F. Sutherland), *586.
——Fans, Method of installing ball bearings in vertical ceiling (W. T. Claytor, Jr.), *479.
——Foundries can be prolonged, By these methods the life of equipment in, *320.
——Lubrication of power transmission equipment (William Staniar), *556.
——Motor bearing trouble caused by overhung pinion, 264.
——Oil in the bearings, Keeping the (B. F. C.), 12.
——Paper-making imposes conditions of severe service (H. D. Fisher), *326.
——Power transmission through steel shafting (William Staniar), *301.
——Types of bearings used in transmission of power (William Staniar), *344.
——Woodworking plants maintain full efficiency of equipment, How two, *296.
Belts (see also Drives and power transmission).
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Chemical plant, Combating corrosion in a (Eric Jensen), *315.
——Drive for paper machines, Use of speed reducer and belt, *587.
——Fabric-base belts, Transmission of power by (William Staniar), *133.
——Group drives improve operating conditions, Mechanical refinements of, *197.
——Idler corrects improper belt installation, *586.
——Leather industry to convene on business practice, Belting, 560.
——Linestart motors require wider pulleys and wider belts (J. R. Hopkins), 372.
——Maintenance and inspection of leather belts (J. R. Hopkins), *447.
——Paper-making imposes conditions of severe service (H. D. Fisher), *326.
——Power transmission by leather belting (William Staniar), *85.
——Prices of leather belting going down? Are, 422.
——Replacing endless belts (R. H. Kasper), 588.
——Safeguarding equipment for power transmission (William Staniar), *626.
——Safety bar to prevent damage from falling belts (W. T. Claytor, Jr.), *264.
——Short-center belt drives, Power transmission by (William Staniar), *185.
——Static electricity on belts, Research reduces fire hazard from (editorial comment), 238.
——Static on belts be prevented? Can formation of (W. F. Schaphorst), 83.
——Steel industry, Severe service as exemplified in the, *274.
——Tension, Measuring belt (Roy C. Moore), 647.
——Transmission of power to the driven machine (William Staniar), *2.
——Variable speed units, Power transmission through speed reducers and (William Staniar), *515.
——Wabble? What causes these belts to (F. H. Willard), 83.
——When to replace belts, *160.
Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
Blowers (see Fans, and Ventilation).
Brakes:
——Inexpensive design changes are often helpful (Grady H. Emerson), 97.
Book reviews (see also Practical books and trade literature), 103, 122, 246, 617.
Brick Plant, Modern drives and materials-handling equipment mean low power consumption in this paving (Roy C. Wallis), *490.
Brushes (see Motor reconnection and repair, also Motor operation).
Budgeting upkeep keeps down expenses (B. A. Franklin), *622.
Buildings (see Plant, the).

C

Cables (see also Wiring, and Rope).
——Cable extension for industrial electric locomotives (R. K. Hoke), *11.
——Examples of how not to arrange cables in manholes, Horrible, *526.
——Hemp-cord copper cable break? Why does this (A. W. K. Billings), 205.
——Steel industry, Severe service as exemplified in the, *274.
Candy makers, Organization for plant operation and maintenance (W. A. Beck), *340.
Cement, Offsetting wear and tear on equipment in making, *281.
Census of manufactures, Small plants to contribute to next (editorial comment), 462.
Chain drives (see also Drive).
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——For long conveyor chains, Constant-speed drives (Robert W. Drake), *390.
——Limitations of roller chain drives (Woodward Warrick), *254.
——Power transmission through chains (William Staniar), *471.
——Terms used in connection with chain drives, 96.
Chains (see also Conveyors).
——When to replace chains and sprockets, *154.
Charts (see Records and INDUSTRIAL ENGINEERING'S data sheets).
Chemical plant, Combating corrosion in a (Eric Jensen), *315.
Chinaware factory furnishes examples of the ceramic industry's severe service problems, A (A. A. Wells), *311.
Clutches (see Power transmission mechanical).
——Power transmission through friction clutches (William Staniar), *402.
——Speed and power, Clutch (William Staniar), 494.
——When to replace couplings and clutches, 132.
Codes:
——Safety code for mechanical power transmission, 314.
Coils (see also Motor coils and Motor winding).
——Lightning arrester choke coils to pass out of the picture, 610.
Coming events (see Meetings forthcoming).
Communication (see also Signals).
——Plants, Communication within industrial (Frank E. Gooding), *510.
Commutator (see also Motor operation, Motor brushes, Motor reconnection and repair).
——Mica V-ring of commutator, Trouble with (S. S. Wolff), 260; (G. P. Chatfield) 260.

*Indicates illustrated articles

UNIVERSITY OF MINNESOTA LIBRARY

Ex 6805

C

——Trouble with this commutator, What is causing (R. F. Emerson), 205, (W. T. E.), 205.
Compensators (see Control).
Conduit (see also Wiring).
——Reshaped in place for new construction, Installed conduit (J. E. Beneze), *210.
Conferences (see Meetings).
Contactors (see Control).
Control:
——Automatic heat for an automatic station, *169.
——Automatic control for board tipple (H. W. Wikle), *364.
——Auto-starters to changed conditions, Adapting (C. A. Johnson), *580, *641.
——Automatic motor speed variation during cutting operations (P. T. Van Bibber), *251.
——Compensator for 440-volt operation, Adopting 220-volt (T. H. Arnold), *263.
——Contactors and similar equipment, What goes on inside the d.c. electro-magnet when operating (H. D. James), *94.
——Crane, What is the best method of stopping this (W. R. McBrayer), *164; (R. F. Emerson), *165; (F. H. Rooney), 206; (S. W. Stearns), 419.
——Limit switches—their care and use, Electric (J. A. Jackson), *338.
——Modern controls, Flexibility and ease of operation are obtained by (H. M. Myers and J. M. Wade), *420.
——Motor-generator set, Emergency starter for a (Grady H. Emerson), 412.
——Motor speed, Series-parallel and other methods of controlling (H. D. James), *568.
——Motor speeds, Two methods of adjusting (H. D. James), *366.
——Motor? What causes poor starting of this (R. F. Emerson), *478; (Jas. B. Holston), 645.
——Multi-speed motors offer to industry, What (R. H. Rogers), *611.
——Parts, When to replace electrical control, *114.
——Regulators, Effects of induction voltage (C. O. Von Dannenberg), *164.
——Relay plungers, Eliminating trouble with (Grady H. Emerson), 83.
——Relay, What is the theory of this (Grady H. Emerson), 164.
——Rheostat for emergency service, Simple water (Albert Bourdo), 479.
——Sawmill equipment, Locking floor button controls, *639.
——Slipring motor, Reducing speed of (R. F. Emerson), *370; (E. H. Laabs), 370; (C. O. Von Dannenberg), 371.
——Starters and speed controllers for electric motors (H. D. James), *228.
——Steel industry, Severe service as exemplified in the, *274.
——Surge ring failure due to starting current inrush (R. K. Hoke), 210.
——Switches, Emergency inclosures for open knife (Charles A. Peterson), *263.
——Whistle serves as code call, Electrically controlled, *412.
Conventions (see Meetings).
Conveyors (see Handling materials).
——Drives for long conveyor chains, Constant-speed (Robert W. Drake), *390.
——Drives for long conveyor chains, Variable-speed (Robert W. Drake), *439.
——Materials handling equipment a necessary service to production in the metal working industry, *65.
——Steel industry, severe service as exemplified in the, *274.
Corrosion:
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Chemical plant, Combating corrosion in a (Eric Jensen), *315.
Cost:
——Belting going down? Are prices of leather, 422.
——Budgeting upkeep keeps down expenses (B. A. Franklin), *622.
——Gas 16 per cent, electricity 35 per cent, water 43 per cent, How a plant engineering department reduced the cost of (E. J. Smith), *247.
——Lighting industry, Economic aspect involved in high (Frank A. Hansen), *561.
——Water, A dollar twenty-seven per person per year for drinking (Charles L. Hubbard), *77.
——Yearly costs, It takes us three days to determine (H. E. Stafford), *413.
Couplings (see also Power transmission mechanical).
——Power transmission through steel shafting (William Staniar), *301.
——When to replace couplings and clutches, 132.
Cranes (see also Handling materials).
——Brake. Inexpensive design changes are often helpful (Grady H. Emerson), 97.
——Equipment a necessary service to production in the metal working industry, Materials handling, *65.

C

——Foundries can be prolonged, By these methods the life of equipment in, *320.
——Steel industry, Severe service as exemplified in the, *274.
——Stopping this crane? What is the best method of (R. F. Emerson), *165; (F. H. Rooney), 206; (S. W. Stearns), 419; (W. R. McBrayer), *164.

D

Data sheets (see INDUSTRIAL ENGINEERING'S data sheets).
——Electric station design, The incorporation of safety in (V. R. Bacon), 373.
——Motor maintenance, Designing for protection reduces (Paul W. Arnold), *235.
Diagrams (see Records).
Distribution:
——Checking the distribution of purchased power (K. D. Hamilton), *199.
——Distributing 45,000 kw.—how it is done at the Canton plant of the Timken Roller Bearing Company (W. A. Beck), *604.
——High-frequency power (John P. Petrowsky), *7.
——Reducing the light bill (Elton Sterrett), 12.
——Transformer installation insures reliable service, Correct (David R. Dalzell), *69.
Drills (see Tools).
Drives:
——Belt installation, Idler corrects improper, *586.
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Chain drives, Limitations of roller (Woodward Warrick), *274.
——Chains, Power transmission through (William Staniar), *471.
——Chinaware factory furnishes examples of the ceramic industry's severe service problems, A (A. A. Wells), *311.
——Conveyor chains, Constant-speed drives for long (Robert W. Drake), *390.
——Conveyor chains, Variable-speed drives for long (Robert W. Drake), *439.
——Group drive improves operating conditions, Mechanical refinements of, *197.
——Lineshaft be driven? How should this (W. T. E.), 646; (W. E. Sooy), 646; (J. J. Wynhoff), 646.
——Modern drives and materials-handling equipment mean low power consumption in this paving-brick plant (Roy C. Wallis), *490.
——Paper machine, Use of speed reducer and belt drive for, *587.
——Paper-making imposes conditions of severe service (H. D. Fisher), *326.
——Power transmission through speed reducers and variable speed units (William Staniar), *515.
——Steel industry, Severe service as exemplified in the, *274.
——Woodworking plants maintain full efficiency of equipment, How two, *296.

E

Editorial comment:
——A plea for better-traveled plant engineers, 294.
——Accident prevention and the plant engineer, 245.
——Are performance records making your summer work easy? 362.
——Are you ready for the question? 245. 295.
——Are prices of leather belting going down? 422.
——Artificial lighting and efficient continuous operation, 294.
——Business as usual? 625.
——Buyers, sellers and service, 422.
——Coming—a golden jubilee of light, 244.
——Design guards to increase production, 196.
——Don't neglect buildings and auxiliary equipment, 162.
——Electric heat belongs in the modernization program, 162.
——Establishment of stability (excerpt President Hoover's Message to the United States Chamber of Commerce), 625.
——Even grass pays, 579.
——For properly-trained welders only, 463.
——Give equipment a fair chance to render maximum service, 162.
——Golden jubilee of light a tribute to Thomas A. Edison, The, *423.
——Good artificial lighting provides "sunny days," 363.
——Good lighting increases useful work, 525.
——Good plant housekeeping indicates progressive industrial southeast, 244.
——Handicaps in the transportation of materials, 362.
——Have you studied the advantages of short-center drives? 295.
——Heat comes first, 578.
——Here is an issue devoted to replacement, 109.
——Housekeeping for trouble-free components, 462.
——How about your plant fences? 525.

E

——Industry has outgrown its swaddling clothes, 555.
——Industry will do more air conditioning, 422.
——Iron and steel exposition a success in spite of handicap, 363.
——It doesn't cost any more to sit at the table—, 603.
——Let the safety congress help you reduce accidents, 463.
——Let's sweeten the pot, 225.
——Lubrication engineering as an aid to prevention, 162.
——Mechanics lead in intelligence, 47.
——Men responsible for illumination will welcome permanent lighting exhibit (Westinghouse lighting institute), 244.
——Mill supply houses and the plant engineer, 295.
——Modernization's ultimate goal, 578.
——More mechanical handling—fewer accidents, 525.
——Not only what to do and when to do it, but . . . what to do it with, 1.
——Paper, ink and ideas—one of your important engineering tools, 579.
——Philosophy of modernization, The, 489.
——Physical defects in plant a challenge to engineering ability, 68.
——Pick the dollars out of your scrap pile, 362.
——Plant engineers and their function, 433.
——Plant engineering opportunities in New England, 624.
——Rain or snow and colder, 625.
——Ratio of lighting load to power consumption, 625.
——Recommended—exposure to the modernization germ, 524.
——Recommendation for census data on unemployment—a movement worthy of support, 245.
——Replacement is a function of prevention, 162.
——Research reduces fire hazard from static electricity on belts, 238.
——Safety through leadership, 579.
——See you at Pittsburgh? (equipment show), 244.
——Severe service, A homely analogy introduces this issue devoted to, 273.
——Simplification of industrial truck tires deserves your support, 363.
——Slow driver—slow traffic, 524.
——Small plants to contribute to next census of manufactures, 462.
——Spare-parts stocks are insurance against breakdowns, 196.
——Substituting instruction for reprimands, 624.
——Ten horsepower for one—an incident in industrial progress, 578.
——The push-the-job man, 196.
——Think straight about housekeeping in industry, 177.
——To buy or make replacement parts, *119.
——Two car loads of good will and progressiveness, 579.
——Volume eighty-seven, 47.
——We have moved to Chicago, 57.
——What becomes of the men replaced by machines? 45.
——What severe service is, 294.
——When guesswork comes in efficiency goes out, 68.
——When it comes to drinking water the best is none too good, 68.
——When summer comes—, 339.
——While the business sun is shining follow the old advice, 68.
——Yes, we all pay "fire tax," 462.
——"You'll have to wait until Mr. Blank comes back to the office," 578.
——Your responsibilities in handling materials, 389.
Efficiency:
——Goes out, When guess work comes in (editorial comment), 68.
Electromagnets (see Magnets).
Employment:
——Extra men be hired or work sublet, Should (A. C. Barker), 418; (Carl A. Wagner), 418.
——Unemployment—a movement worthy of support, Recommendation for census data on (editorial comment), 245.
Engineers (see Plant Engineering).
Engineering (see Plant engineering).
Equipment:
——Battery charging equipment for electric trucks and tractors (H. M. Martin), *191.
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Electrical modernization without production delay (Wm. B. Ferguson), *530.
——Fire department—a necessary adjunct to production, The industrial (T. J. O'Connor), *434.
——Fire extinguishers from freezing, Keep the, 560.
——Fire protection equipment, How to inspect the (A. G. Smith), *151.
——Fire, Protect production against (A. C. Hutson), *520.
——Foundries can be prolonged, By these methods the life of equipment in, *320.

*Indicates illustrated articles

En620.5
fIn206

E

——Life of industrial equipment, normal service—severe service, *308.
——Lubrication of power transmission equipment (William Staniar), *556.
——Lubrication of equipment, Practical tips on (W. E. Warner), 411.
——Machinery, Concerning junked, used and rebuilt (George Rice), 537.
——Materials handling equipment a necessary service to production in the metal working industry, *65.
——Materials-handling equipment means low power consumption in this paving-brick plant, Modern drives and (Roy C. Wallis), *490.
——Mechanical aids to systematized production (J. L. Cochran), *499.
——Neglect buildings and auxiliary equipment, Don't (editorial comment), 162.
——New, *50, *104, *170, *218, *266, *333, *382, *425, *481, *541, *593, *648.
Review section, *14.
Review section, contents of, 13.
Review section list of manufacturers, 43.
——New versus old machinery (George Rice), 582.
——Not only what to do and when to do it, but what to do it with (editorial comment), 1.
——Oven doors, Wedge and roller prevent wear and tear on, *587.
——Paper-making imposes conditions of severe service (H. D. Fisher), *326.
——Rack for bar stock, How to make sectional, *638.
——Reel facilitates handling heavy cables, *638.
——Replacement, Here is an issue devoted to (editorial comment), 109.
——Replacement parts, To buy or make (editorial comment), *119.
——Replacement, While the business sun is shining follow the old advice (editorial comment), 68.
——Safeguarding equipment for power transmission (William Staniar), *626.
——Salvaging, Who should do the (see Are you ready for the question?).
——Service, Give equipment a fair chance to render maximum (editorial comment), 162.
——Steel industry, Severe service as exemplified in the, *274.
——Wear and tear on equipment in making cement, Offsetting, *281.
Events coming (see Meetings forthcoming).
Exhibits (see Meetings, Announcements and Meetings forthcoming).
Expositions (see Meetings, Announcements and Meetings forthcoming).

F

Fans (see also Ventilation).
——Bearings in vertical ceiling fans, Method of installing ball (W. T. Claytor, Jr.), *479.
——Shop ventilator made from truck fan, Emergency (Henry Simon), *97.
Fire protection (see Safety).
Fixtures (see also Tools and Accessories).
——Lighting fixture, Improved lathe (Charles A. Peterson), *12.
——Plan holder for the machine shop, Handy (G. A. Luers), *11.
——Stators while rewinding, Frame for holding small a.c. (John H. Schoenberger), *412.
Floors (see Plant).
Forum (see also Are you ready for the question?).
——The plant engineer's forum (F. M. Gibson), *6, *74, *166, *194, *252, *306.
Foundries can be prolonged, By these methods the life of equipment in, *320.
Fuses:
——Ferrules for tools out of old fuses, Making (R. M. Thomas), 169.

G

Gears (see also Pinions).
——Chinaware factory furnishes examples of the ceramic industry's problems, A (A. A. Wells), *311.
——Horsepower of spur gearing, Charts for determining the (data sheet), *469, *601.
——Plaster cast helps to visualize gear tooth wear (E. S. Sawtelle), *168.
——Power transmission through speed reducers and variable speed units (William Staniar), *515.
——Safeguarding equipment for power transmission (William Staniar), *626.
——Woodworking plants maintain full efficiency of equipment, How two, *296.
Genealogy:
——Volume eighty-seven (editorial comment), 47.
Generators (see Motors).
Grease (see Lubrication).
Grinders:
——Improvised grinder for turning hard steel rollers (Joseph M. Spitzer), 211.
——Uses for a disk grinder in the repair shop (Donald A. Hampson), 365.

H

Handling materials (see also Conveyors, Cranes, Hoists, Trucks, etc.).
——Accidents, More mechanical handling—fewer (editorial comment), 525.
——Auxiliary devices prove their usefulness in materials-handling systems (J. C. Siegesmund), *565.
——Crane hooks that facilitate handling of flat objects (R. M. Thomas), *640.
——Materials handling equipment—a necessary service to production in the metal working industry, *65.
——Mechanical aids to systematized production (J. L. Cochran), *499.
——Modern drives and materials-handling equipment mean low-power consumption in this paving-brick plant (Roy C. Wallis), *490.
——Problem, 200 tons of parts daily—our materials-handling (Ray G. Rech), *614.
——Responsibilities in handling materials, Your (editorial comment), 389.
——Transportation of materials, Handicaps in the (editorial comment), 362.
——Unusual case of trouble with mine hoist motor (Grady H. Emerson), 168.
——What is the best method of stopping this crane? (W. R. McBrayer), *164; (R. F. Emerson), *165.
Hangers (see Shafting).
Heating:
——Automatic heat for an automatic station, *169.
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Chinaware factory furnishes examples of the ceramic industry's severe service problems, A (A. A. Wells), *311.
——Electric heat belongs in the modernization program (editorial comment), 524.
——First, Heat comes (editorial comment), 578.
——Oil pipe line, Method of heating (D. W. I.), 259; (Harry C. Myers), 259.
Hoists (see Handling materials).
Housekeeping (see Plant housekeeping).

I

Idlers (see Belts).
Illumination (see Lighting).
Index:
——New equipment review, 13.
——New equipment manufacturers, 43.
Industrial Engineering's data sheets:
——Carbon brush maintenance and trouble chart, 660.
——Gearing, Charts for determining the horsepower of spur, *469.
——Gearing, Charts for determining the horsepower of spur, *601.
——Design of stairs, ladders, ramps and handrails, Notes on, *431.
——Metal partitions for toilets and showers (data sheet), *432.
——Motor troubles and how to remedy them, Symptoms and causes of, 657.
——Resuscitation by the prone pressure method, *375.
Inspection and maintenance:
——Anchor bolt that saves time in setting machines (Fred C. Wood), *264.
——Arc-welding equipment and still expect good results, Why you cannot neglect (C. N. Schafer), *58.
——Battery charging equipment for electric trucks and tractors (H. M. Martin), *191.
——Battery trucks and tractors, When to replace storage, *158.
——Bearings, When to replace anti-friction, *138.
——Belts, Maintenance and inspection of leather (J. R. Hopkins), *447.
——Belt tension, Measuring (Roy C. Moore), 647.
——Belts, When to replace, *160.
——Brush maintenance and trouble chart, Carbon (data sheet), 660.
——Buildings and auxiliary equipment, Don't neglect (editorial comment), 162.
——Busbars, Method of cleaning (Frederick J. H. Krause), 585.
——Chain and sprockets, When to replace, 154.
——Circuit, Use of lamp in fuse block to indicate short (James P. Marshall), 410.
——Commutator, Trouble with mica V-ring of (S. S. Wolff) 260, (G. P. Chatfield) 260.
——Control parts, When to replace electrical, *114.
——Couplings and clutches, When to replace, 132.
——Equipment in making cement, Offsetting wear and tear on, *281.
——Expansion shields, Simple method of tightening (James P. Marshall), 263.
——Fire protection equipment, How to inspect the (A. G. Smith), *151.
——Floor maintenance in a paper mill, *234.
——Instruments, Reducing maintenance cost on portable (Elbert E. Greenberg), *169.
——Insulation faults, Radio waves search out, *98.
——Lighting system should be replaced, Defective units in the (J. J. McLaughlin), *116.
——Meters without checking connections, Testing (E. J. Elvish), *477.
——Motor loads, Why it is advisable to check up on (C. W. Drake), *318.
——Motor maintenance, Designing for protection reduces (Paul W. Arnold), *235.
——Motor trouble, How organized inspection prevents (C. W. Allen), *444.
——Motor troubles and how to remedy them. Symptoms and causes of (data sheet), 657.
——Motor, Unusual case of trouble with mine hoist (Grady H. Emerson), 168.
——Organized for maintenance and plant housekeeping, How we are (W. G. Ross), *178.
——Pipe and tubes, Emergency methods of bending (W. F. Schaphorst), 586.
——Power, Measuring three-phase (Earl R. Witzel), *584; (C. O. Von Dannenberg, *584.
——Pulley securely on shaft, Plate to hold wood (Murray MacDonald), *263.
——Rain or snow and colder (editorial comment), 625.
——Records are vital in service to production, *110.
——Reducing maintenance cost on portable instruments (Elbert E. Greenberg), *169.
——Replacement, Co-ordinate the functions of the electrical repair shop for (W. A. Beck), *145.
——Replacement parts, To buy or make (editorial comment), *119.
——Replacement, When summer comes— (editorial comment), 339.
——Rope cables, Pointers on the care of wire (H. C. Charles), 588.
——Rope to prevent unlaying, How to seize wire, *564.
——Schedule basis, Putting maintenance and inspection on a (H. E. Stafford), *140.
——Service, Give equipment a fair chance to render maximum (editorial comment), 162.
——Substations need systematic maintenance for dependable operation, Automatic (G. F. Jones), *394.
——Surge ring failure due to starting current inrush (R. K. Hoke), 210.
——Switches—their care and use, Electric limit (J. A. Jackson), *358.
——Systematic inspection, maintenance and lubrication (L. B. Hornberger), *156.
——Tools, When to replace portable electric, *149.
——Transformer maintenance for continuity of service, First aids in (D. R. Dalzell), *458.
——Trucks, Replacements for electrical industrial (C. B. Crockett), *123.
——Welding saves the day, *618.
——Welding or have it done by a contract shop, Shall we do our own maintenance (M. Hallen), *232.
——Woodworking plants maintain full efficiency of equipment, How two, *296.
——Work sublet? Should extra men be hired or (A. C. Barker) 418, (Carl A. Wagner), 418.
Instruments (see Meters).

L

Lamps (see also lighting).
——Breakage of lamps from vibration, Preventing (L. E. Beneze), 169.
——Filament, Vibration and its effect on lamp (Allison J. Thompson), 416.
Lighting (see also Lamps).
——Artificial lighting provides "sunny days," Good (editorial comment), 363.
——Colors for industrial interiors, Obtain more light by using proper (T. J. Maloney), *571.
——Defective units in the lighting system should be replaced at once (J. J. McLaughlin), *116.
——Economic aspects involved in high-lighting industry (Frank A. Hansen), *561.
——Exhibit, Westinghouse opens light, 332.
——Floodlighting can do, What, *623.
——Golden jubilee of light, Coming—a (editorial comment), 244.
——High-lighting industry with 54.3 foot-candle intensity (Frank A. Hansen), *495.
——Housekeeping tools and methods for the plant lighting system (Robert L. Zahour), *212.
——Improved lathe lighting fixture (Charles A. Peterson), *12.
——Paint can do—, What, *540.
——Ratio of lighting load to power consumption (editorial comment), 625.
——Reducing the light bill (Elton Sterrett), 12.
——(Westinghouse Lighting Institute) Men responsible for illumination will welcome permanent lighting exhibit (editorial comment), 244.
——Work, Good lighting increases useful (editorial comment), 525.
Lightning Arresters:
——Choke coils to pass out of the picture, 610.
Lineshaft (see also Shafting).
——Bearings used in transmission of power, Types of (William Staniar), *344.

*Indicates illustrated articles

489547

L

——Chinaware factory furnishes examples of the ceramic industry's severe service problems, A (A. A. Wells), *311.
——Driven? How should this lineshaft be (W. T. E.), 646; (W. E. Sooy), 646; (J. J. Wynhoff), 646.
——Group drives improve operating conditions, Mechanical refinements of, *197.
——Power transmission through steel shafting (William Staniar), *301.
——Woodworking plants maintain full efficiency of equipment, How two, *296.
Literature (see Trade literature and Book reviews).
Locomotives:
——Special cable extension for industrial electric (R. K. Hoke), *11.
Lubrication:
——Automatic lubrication takes its place in service to production (Allen F. Brewer), *215.
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Engineering as an aid to prevention (editorial comment), 162.
——Equipment a fair chance to render maximum service, Give (editorial comment), 162.
——Keeping the oil in the bearings (B. F. C.), 12.
——Power transmission equipment, Lubrication of (William Staniar), *556.
——Production, Upon lubrication depends continuity of, 509.
——Systematic inspection, maintenance and lubrication (L. B. Hornberger), *156.
——Tips on lubrication of equipment, Practical (W. E. Warner), 411.
——Trucks and trailers on the spot, Scheduled lubrication puts, *609.
——Who shall do the oiling? (See Are you ready for the question?).
——Woodworking plants maintain full efficiency of equipment, How two, *296.

M

Machinery (see also Tools and Accessories).
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Foundries can be prolonged, By these methods the life of equipment in, *320.
——Lathe lighting fixture, An improved (Charles A. Peterson), *12.
——Machines, What becomes of the men replaced by (editorial comment), 47.
——New versus old machinery (George Rice), 582.
——Rebuilt machinery, Concerning junked, used and (George Rice), 537.
——Salvaging, Who should do the (see Are you ready for the question?).
——Setting machines, Anchor bolt that saves time in (Fred C. Wood), *264.
——Shearing machine, Guard for power (P. J. Edmonds), *98.
Magnets (see also Motor control).
——Alternating-current magnets, Features that distinguish (H. D. James), *467.
——Demagnetizing motor shafts, method of (Harry W. Benton), 480.
——Wire sizes for electromagnets, How to determine (H. B. Brooks), 349.
Maintenance (see Inspection and).
Manufacturers, index of, 43.
Materials handling (see Handling materials).
Meetings:
——Iron and steel exposition a success in spite of handicaps (editorial comment), 363.
——Mill supplies convention, High lights from the, 330.
——P. T. A., Third regional meeting held by, 148.
——Rope research to continue, Conference recommends wire, 537.
Meetings forthcoming, 56, 108, 176, 93, 272, 286, 338, 378, 388, 430, 466, 488, 508, 539, 554, 560, 600, 656.
Men (see also Employment).
——Mechanics lead in intelligence (editorial comment), 47.
——Push-the-job man, The (editorial comment), 196.
——Welders only, For properly-trained (editorial comment), 463.
——What becomes of the men replaced by machines? (editorial comment), 47.
——Unemployment—a movement worthy of support, Recommendation for census data on (editorial comment), 245.
Meters:
——Constant with odd-size paper? What meter (R. E. Murphy), 84.
——Electrical testing instruments, How to connect and use (E. S. Lincoln), *89. Correction, 214.
——Motor loads, Why it is advisable to check up on (C. W. Drake), *318.
——Power, Checking the distribution of purchased (K. D. Hamilton), *199.
——Reducing maintenance cost on portable instruments (Elbert E. Greenberg), *169.
——Stethoscope test for welded joints, 587.
——Testing meters without checking connections (E. J. Elvish), *477.

M

——Transformer maintenance for continuity of service, First aids in (D. R. Dalzell), *458.
Modernization:
——Electrical modernization without production delay (William B. Ferguson), *530.
——Heat belongs in the modernization program, Electric (editorial comment), 524.
——Housekeeping is essential to our business, Good plant (Dr. M. A. Dittmer), *553.
——Motor windings—how to replace an old bar and end connector winding by the diamond two-layer type, Modernizing old (A. C. Roe), *635.
——Motor windings, Modernizing old (A. C. Roe), *538.
——Philosophy of modernization, The (editorial comment), 489.
——Recommended—exposure to the modernization germ (editorial comment), 524.
——Safety in modernization, And (H. P. Osborne), *527.
——Slow driver—slow traffic (editorial comment), 524.
——Two car loads of good will and progressiveness (editorial comment), 578.
——Ultimate goal, Modernization's (editorial comment), 578.
Motor Application:
——Across-the-line motors a discussion of their characteristics and use (Jas. B. Holston), *99.
——Balancer set to make three-wire system, Using (G. Williamson), *204.
——Battery charging equipment for electric trucks and tractors (H. M. Martin), *191.
——Bearing trouble caused by overhung pinion, Motor, 264.
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Changes are required with this generator? What? (J. F. Lincoln), 206.
——Chemical plant, Combating corrosion in a (Eric Jensen), *315.
——Chinaware factory furnishes examples of the ceramic industry's severe service problems, A (A. A. Wells), *311.
——Designing for protection reduces motor maintenance (Paul W. Arnold), *235.
——Generators in parallel give trouble, Operation of three (G. R. Lieber), 418; (Hugh A. Black), 418.
——Generator, What changes are required with this (P. P. Scribante), 371.
——High-Frequency Power Simplifies the Motor Application Problem (John P. Petrowsky), *7.
——Linestart motors require wider pulleys and wider belts (J. R. Hopkins), 372.
——Multi-speed motors offer to industry, What (R. H. Rogers), *611.
——Operating 60-cycle motor on 50 cycles (R. P. Guildford), 647; (R. F. Emerson), *647.
——Paper-making imposes conditions of severe service (H. D. Fisher), *326.
——Selsyn motor, Operation of (C. O. Von Dannenberg and R. F. Emerson), 84.
——Single-phase motors, Choice of voltage for operating (R. F. Emerson), 645; (Edward A. Gibbs), 645; (L. C. Hartman), 645.
——Steel industry, Severe service as exemplified in the, *274.
——Synchronous motor causes line surge (William B. Ferguson), *259; (C. O. Von Dannenberg), 259.
——Synchronous motors offer to industry, What (R. H. Rogers), *575.
——Torque, Method of calculating (C. O. Von Dannenberg), 81.
——Wear and tear on equipment in making cement, Offsetting, *281.
——Woodworking plants maintain full efficiency of equipment, How two, *296.
Motor Brushes:
——Chart, carbon brush maintenance and trouble (data sheet), 660.
——Holders keep these machines from sparking? Will new brush (W. T. E.), 165; (Earl R. Witzel), 260.
——Shifting brush yoke, Trouble with generator due to (Edward D. Carter), 411.
——Shifting brushes corrected instability of d.c. motor (E. J. Sacco), 211.
Motor coils (see also Motor windings).
——Layer-wound pulled coils for partly-closed slot machines (A. C. Roe), *207.
——Locating short-circuited coils in A.C. motors (Richard Bromley), 83; (R. L. Pace), 83.
——Replacing obsolete dropped-bottom-cell coils with the two-coil-per-slot pulled type (A. C. Roe), *261.
——Stripping stators and armatures, Easy method of (Carl A. Wagner), 480.
——Surge ring failure due to starting current inrush (R. K. Hoke), 210.
Motor Commutator:
——Trouble encountered in placing new commutator in service (Fred Hartman), 567.

M

——What is causing trouble with this commutator (E. D. Carter), 82; (Edward A. Gibbs), 82; (R. F. Emerson), 205; (W. T. E.), 205.
Motor Operation:
——Air for motors in heated buildings, Outside (W. T. Claytor), *97.
——Arc-welding equipment and still expect good results, Why you cannot neglect (C. N. Schafer), *58.
——Bearing currents caused by solenoid shaft oscillator (W. F. Sutherland), *586.
——Bearing trouble caused by overhung pinion, Motor, 264.
——Brush-holders keep these machines from sparking, Will new (W. T. E.), 165; (Earl R. Witzgel), 260.
——Brush maintenance and trouble chart, Carbon (data sheets), 660.
——Brush yoke, Trouble with generator due to shifting (Edward D. Carter), 411.
——Collector rings, Preventing brush marks on (Philip N. Emigh), 81; (H. J. Achee), 81.
——Commutator, What is causing trouble with this (R. F. Emerson), 205; (W. T. E.), 205; (E. D. Carter), 82; (Edward A. Gibbs), 82.
——Diagnosis of electrical trouble does not pay, Hasty (Grady H. Emerson), 479.
——Field magnetism, Exciter loses (H. J. Achee), 84.
——Generators in parallel give trouble, Operation of three (G. R. Lieber), 418; (Hugh A. Black), 418.
——Inspection prevents motor trouble, How organized (C. W. Allen), *444.
——Instability of d.c. motor, Shifting brushes corrected (E. J. Sacco), 211.
——Loads, Why it is advisable to check up on motor (C. W. Drake), *318.
——Mica V-ring of commutator, Trouble with (S. S. Wolff), 260; (G. P. Chatfield), 260.
——Mine hoist motor, Unusual case of trouble with (Grady H. Emerson), 168.
——Operating 60-cycle motor on 50 cycles (R. P. Guildford), 647; (R. F. Emerson), *647.
——Slipring motor, reducing speed of (R. F. Emerson), *370; (E. H. Laabs), 370; (C. O. Von Dannenberg), 371.
——Sparking, Will new brush-holders keep these machines from (Earl R. Witzel), 260; (W. T. E.), 165.
——Speeds, Two methods of adjusting motor (H. D. James), *366.
——Starters and controllers for electric motors (H. D. James), *228.
——Starting of this motor? What causes poor (R. F. Emerson), *478; (Jas. B. Holston), 645.
——Steel industry, Severe service as exemplified in the, *274.
——Surge ring failure due to starting current inrush (R. K. Hoke), 210.
——Synchronous motor causes line surge (William B. Ferguson), *249; (C. O. Von Dannenberg), 259.
——Troubles and how to remedy them, Symptoms and causes of motor (data sheets), 657.
——Trouble encountered in placing new commutator in service (Fred Hartman), 567.
——Wear and tear on equipment in making cement, Offsetting, *281.
Motor reconnection and repair:
——Changing a twelve-pole motor to eight poles (A. C. Roe), *639.
——Changing speed of single-phase motor, Troubles met in (Henry F. Kaelin), *364.
——Commutator in service, Trouble encountered in placing new (Fred Hartman), 567.
——Coils for partly-closed-slot-machines, Layerwound pulled (A. C. Roe), *207.
——Coils in a.c. motors, Locating short-circuited (Richard Bromley), 83; (R. L. Pace), 83.
——Coils with the two-coil-per-slot pulled type, Replacing obsolete dropped-bottom coil (A. C. Roe), *261.
——Diagnosis of electrical trouble does not pay, Hasty (Grady H. Emerson), 479.
——Generator, What changes are required with this (P. P. Scribante), 371.
——Insulation faults, Radio waves search out, *98.
——Laminations, Method of filling holes in (Carl A. Wagner), 81.
——Mica undercutting tool, Details of simple (W. F. Burket), *168.
——Modernizing old motor windings—how to replace an old bar and end connector winding by the diamond two-layer type (A. C. Roe), *635.
——Shafts, Method of demagnetizing motor (Harry W. Benton), 480.
——Stripping stators and armatures, Easy method of (Carl A. Wagner), 480.
——Surge ring failure due to starting current inrush (R. K. Hoke), 210.
Motor winding:
——Chord factor of concentric winding (A. C. Roe), 49.

*Indicates illustrated articles

M

——Modernizing old motor windings (A. C. Roe), *538.
——Modernizing old motor windings—how to replace an old bar and end connector winding by the diamond two-layer type (A. C. Roe), *635.
——Replacing an old involute winding by the diamond two-layer type (A. C. Roe), *407.
——Replacing an old shove-through winding by the threaded-in type (A. C. Roe), *125.
——Stators while rewinding, Frame for holding small a.c. (John H. Schoenberger), *412.
——Terms used in calculating motor windings, Meaning of (A. C. Roe), *371.

N

New equipment (see Equipment).

O

Oil (see also Lubrication).
——Heating oil pipe line, Low-resistance joints method of (D. W. I.), 259; (Harry C. Myers), 259.
——Keeping the oil in the bearings (B. F. C.), 12.
Organization:
——Housekeeping, How we are organized for maintenance and plant (W. G. Ross), *178.
——Housekeeping in industry, Think straight about (editorial comment), 177.
——Plant engineering, A practical-ideal organization for (L. C. Morrow), *504.
——Plant engineering, National Cash Register, organization for (E. D. Smith), *464.
——Plant operation and maintenance, Organization for, E. J. Brach & Sons (W. A. Beck), *340.
Ovens (see also Heating and Ventilation).
——Doors, Wedge and roller prevent wear and tear on oven, *587.
Oxy-acetylene welding (see Welding).

P

Paint and painting:
——How can better painting results be obtained? (Roy C. Sheeler), 49.
——Light by using proper colors for industrial interiors, Obtain more (T. J. Maloney), *571.
——Methods, Fighting rust and corrosion with better painting (Roy C. Sheeler), *182.
——Piping systems, Scheme to identify, 153.
——Pyroxylin finishes in maintenance painting, The place of (Roy C. Sheeler), *351.
——Spend for replacement what you save by scheduled painting of structural parts and buildings (Roy C. Sheeler), *129.
——Unused paint, How to keep (Chas. A. Peterson), 204; (Roy C. Sheeler), 419.
——What paint can do—, *540.
Paper-making imposes conditions of severe service (H. D. Fisher), *326.
Pinion (see also Gears and Drives).
——Motor bearing trouble caused by overhung pinion, 264.
——Plaster cast helps to visualize gear tooth wear (E. S. Sawtelle), *168.
Piping and pipes:
——Bending pipes and tubes, Emergency method of (W. F. Schaphorst), 586.
——Heating oil pipe line, Method of (D. W. I.), 259; (Harry C. Myers), 259.
——Laying off angles with a water mark (W. I. G.), *97.
——Scheme to identify piping systems, 153.
Plant engineering (see also Industrial Engineering's data sheets).
——Accident prevention and the plant engineer (editorial comment), 245.
——Budgeting upkeep keeps down expenses (B. A. Franklin), *622.
——Business as usual? (editorial comment), 25.
——Cleaning, Who shall do the (see Are you ready for the question?).
——Census of manufactures, Small plants to contribute to next (editorial comment), 462.
——Electric station design, The incorporation of safety in (V. R. Bacon), 373.
——Fire hazards from static electricity on belts, Research reduces, 238.
——Flywheel, Determining safe speed of (W. F. Schaphorst), *370.
——Forum (see Forum).
——Function, Plant engineers and their (editorial comment), 433.
——Gear tooth wear, Plaster cast helps to visualize (E. S. Sawtelle), *168.
——Industry has outgrown its swaddling clothes (editorial comment), 555.
——It doesn't cost any more to sit at the table (editorial comment), 603.
——Motor windings, Meanings of terms used in calculating (A. C. Roe), *371.
——Oiling, Who shall do the (see Are you ready for the question?).
——Organization for plant engineering, A practical-ideal (L. C. Morrow), *504.

P

——Organization for plant engineering, National Cash Register (E. D. Smith), *464.
——Organization for plant operation and maintenance (W. A. Beck), *340.
——Paper, ink, and ideas—one of your important engineering tools (editorial comment), 579.
——Plant engineering opportunities in New England (editorial comment), 624.
——Physical defects in plant a challenge to engineering ability (editorial comment), 68.
——Salvaging? Who shall do (See Are you ready for the question?)
——Service departments to the general manager, The value of efficient (C. S. Proudfoot), 393.
——Should the plant engineering department have the right to question orders? (See Are you ready for the question?)
——Slow driver—slow traffic (editorial comment), 524.
——Substituting instructions for reprimands (editorial comment), 624.
——Ten horsepower for one—an incident in industrial progress (editorial comment), 578.
——Transformers, Determining full-load current on single-phase (Charles F. Cameron), *410.
——What shall be the maintenance policy? (See Are you ready for the question?).
——Wire, Graphical method of finding area of copper (Chas. F. Cameron), *265.
——Wire sizes for electromagnets, How to determine (H. B. Brooks), 349.
Plant Housekeeping:
——Components, Housekeeping for trouble-free (editorial comment), 462.
——Essential to our business, Good housekeeping is (Dr. M. A. Dittmar), *533.
——Organized for maintenance and plant housekeeping, How we are (W. G. Ross), *178.
——Southeast, Good plant housekeeping indicates progressive industrial (editorial comment), 244.
——Think straight about housekeeping in industry (editorial comment), 177.
——Tools and methods for the plant lighting system, Housekeeping (Robert L. Zahour), *212.
——Yards mark the modern plant, Neat, *528.
Plant Service (see also housekeeping, and signals).
——Cleaning? Who shall do the (see are you ready for the question).
——Cost of gas 16 per cent electricity 35 per cent water 43 per cent, How a plant engineering department reduced the (E. J. Smith), *247.
——Drinking water, if you don't have a modern cooling system you probably are paying more than a dollar twenty seven per person per year for (Charles L. Hubbard), *76.
——Drinking water the best is none too good, When it comes to (editorial comment), 68.
——Fire department—a necessary adjunct to production, The industrial (T. J. O'Connor), *434.
——Give equipment a fair chance to render maximum service (editorial comment), 162.
——Records are vital in service to production, *110.
——Transformer installation insures reliable service, Correct (David R. Dalzell), *69.
Plant, the:
——Anchor bolt that saves time in setting machines (Fred C. Wood), *264.
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Brick plant, Modern drives and materials-handling equipment mean low power consumption in this paving (Roy C. Wallis), *490.
——Buildings and auxiliary equipment, Don't neglect (editorial comment), 162.
——Candy makers, Organization for plant operation and maintenance (W. A. Beck), *340.
——Cash register mechanical aid to systematized production (J. L. Cochran), *499.
——Cash Register organization for plant engineering, National (E. D. Smith), *464.
——Cement, Offsetting wear and tear on equipment in making, *281.
——Chemical plant, Combating corrosion in a (Eric Jensen), *315.
——Chinaware factory furnishes examples of the ceramic industry's severe service problems, A (A. A. Wells), *311.
——Expansion shields, Simple method of tightening (James P. Marshall), 263.
——Fences? How about your plant (editorial comment), 525.
——Fire. Protect production against (A. C. Hutson), *520.
——Floors, Hard facts about surfacing concrete (Robert Kaufman and E. C. McFalls), *61.

P

——Floor maintenance in a paper mill, *234.
——Foundries can be prolonged, By these methods the life of equipment in, *320.
——Grass pays, Even (editorial comment), 579.
——Handrails, Notes on design of (data sheet), *431.
——Ladders, Notes on design of (data sheet), *431.
——Organization for plant operation and maintenance (W. A. Beck), *340.
——Paper-making imposes conditions of severe service (H. D. Fisher), *326.
——Partitions for toilets and showers (data sheets), *432.
——Ramps, Notes on design of (data sheet), *431.
——Roller Bearing Company, Distributing 45,000 kw. how it is done at the Canton plant of the Timken (W. A. Beck), *604.
——Stairs, notes on design of (data sheet), *431.
——Steel industry, Severe service as exemplified in the, *274.
——Substations need systematic maintenance for dependable operation, Automatic (G. F. Jones), *394.
——Track crossings, Plant (H. C. Charles), 238.
——Walls against moisture, Sealing plastered (H. V. Smythe), 584, (R. H. Kasper) 584.
——Walls where holes are cut through, Supporting brick (Maurice C. Cockshott) 646, (H. D. Fisher) *646.
——Washing machine plant—200 tons of parts daily—our materials-handling problem (Ray G. Rech), *614.
——Woodworking plants maintain full efficiency of equipment, How two, *296.
Power:
——Checking the distribution of purchased (K. D. Hamilton), *199.
——High-frequency power simplifies the motor application problem (John P. Petrowsky), *7.
——Lines go hay wire, When supply (F. Whitely), 480.
——Low voltage for testing, Emergency sources of (Chas. A. Peterson), *588.
——Ratio of lighting load to power consumption (editorial comment), 625.
——Station design, The incorporation of safety in electric (V. R. Bacon), 373.
Power show, Fourth midwest conference and (announcement), 93.
Power Transmission Mechanical:
——Bearings used in transmission of power, Types of (William Staniar), *344.
——Belt drives, Power transmission by short-center (William Staniar), *185.
——Belting, Power transmission by (William Staniar), *85.
——Belts, Transmission of power by fabric-base (William Staniar), *133.
——Chains, Power transmission through (William Staniar), *471.
——Clutches, Power transmission through friction (William Staniar), *401.
——Couplings and clutches, When to replace, 132.
——Lubrication of power transmission equipment (William Staniar), *556.
——Meeting held by P. T. A., Third regional, 148.
——Pulleys used in transmission of power, Types of (William Staniar), *185.
——Reducers, When to replace geared speed, 128.
——Safeguarding equipment for power transmission (William Staniar), *626.
——Safety code for mechanical power transmission, 314.
——Shafting, Power transmission through steel (William Staniar), *301.
——Speed reducers and variable speed units, Power transmission through (William Staniar), *515.
——Transmission of power to the driven machine (William Staniar), *2.
Practical Books:
——American standards yearbook, 1929 (American Standards Association), 438.
——Arc welding, Lincoln prize papers (McGraw-Hill Book Company), 438.
——A. S. T. M. tentative standards for 1928 (American Society for Testing Materials), 103.
——Code for electricity meters third edition 1928 (National Electric Light Association), 103.
——Code of minimum requirements for heating and ventilation of buildings (American Society of Heating and Ventilating Engineers), 438.
——Direct-current electricity (L. Raymond Smith), 438.
——Discussion of the National Electrical Safety Code (Department of Commerce, Bureau of Standards), 122.
——Domestic sanitary engineering and plumbing (Frank W. Raynes), 103.
——Electric drive practice (Gordon Fox), 246.
——Electrical engineering problems—part II, alternating-current circuits and apparatus (John G. Pertsch, Jr.), 438.

*Indicates illustrated articles

P

——Engineering electricity (Ralph G. Hudson), 246.
——History of mechanical inventions, A (Abbott Payson Usher), 617.
——How to wind direct-current armatures (W. E. Henning), 246.
——Materials Handbook (George S. Brady), 122.
——Mechanical power transmission (William Staniar), 122.
——Plumbing questions and answers (Joseph E. Taggart), 246.
——Problems in alternating-current machinery (Waldo W. Lyon), 103.
——Recent economic changes in the United States, (report of the committee on recent economic changes of the president's conference on unemployed), 246.
——Transformer construction and operation (Emerson D. Reed), 103.

Prevention:
——Accident prevention and the plant engineer (editorial comment), 245.
——Fire, Protect production against (A. C. Hutson), *520.
——Lubrication depends continuity of production, Upon, 509.
——Lubrication engineering as an aid to prevention (editorial comment), 162.
——Replacement is a function of prevention (editorial comment), 162.
——Rust and corrosion with better painting methods, Fighting (Roy C. Sheeler), *182.
——Stocks are insurance against breakdowns, Spare-part (editorial comment), 196.
——Wedge and roller prevent wear and tear on oven doors, *587.

Protection (see Safety, prevention, and painting).

Pulleys:
——Cast iron pulley with broken rim, Repairing (R. M. Thomas), 411.
——Types of pulleys used in transmission of power (William Staniar), *239.
——Wood pulley securely on shaft, Plate to hold (Murray MacDonald), *263.

Pumps:
——Raising hot water with centrifugal pump (R. F. Emerson), 82.

Q

Questions asked and answered, *48, *80, *163, *203, *258, *369, *417, *476, *583, *644.

R

Records and Charts: (see also Industrial Engineering's data sheets).
——Costs, It takes us three days to determine yearly (H. E. Stafford), *413.
——Equipment normal service—severe service, Life of industrial, *308.
——Fire department—a necessary adjunct to production, The industrial (T. J. O'Connor), *434.
——Hand lift trucks, Life of, 314.
——Inspection, maintenance and lubrication keep down production losses at the Budd plant, Systematic (L. B. Hornberger), *156.
——Lighting system, Housekeeping tools and methods for the plant (Robert L. Zahour), *212.
——Maintenance and inspection on a schedule basis, Putting (H. E. Stafford), *140.
——Maintenance and plant housekeeping, How we are organized for (W. G. Ross), *178.
——Motor loads, Why it is advisable to check up on (C. W. Drake), *318.
——Motor trouble, How organized inspection prevents (C. W. Allen), *444.
——Organization for plant engineering, A practical ideal (L. C. Morrow), *504.
——Organization for plant operation and maintenance (W. A. Beck), *340.
——Organization for plant engineering, National Cash Register (E. D. Smith), 464.
——Performance records making your summer work easy? Are (editorial comment), 362.
——Records are vital in service to production, *110.
——Repair shop for replacement, Co-ordinate the function of the electrical (W. A. Beck), *145.
——Salvage and storage must tie in with the replacement program (Henry F. Scott), *143.
——Substations need systematic maintenance for dependable operation, Automatic (G. F. Jones), *394.
—Tool recording system, A simple (M. C. Cockshott), 211.
——Transformers, Determining full-load on single-phase (Charles F. Cameron), *410.
——Wire, Graphical method of finding area of copper (Chas. F. Cameron), *265.

Refrigeration:
——A Dollar Twenty-Seven per Person per year for Drinking Water (Charles L. Hubbard), *76.

R

Regulators (see Control).
Relay (see Control).
Repair shop:
——Co-ordinate the functions of the electrical repair shop for replacement (as told to W. A. Beck), *145.
Reports (see Records).
Research (see Plant engineering).
Review (see Equipment, new).
Rheostats (see Control).
Rope:
——Seize wire rope to prevent unlaying, How to, *564.
——Wire rope before ordering, It pays to know (Dale M. Perrill), *377.
——Wire rope before ordering, It pays to know your (discussion) (K. D. Rothschild), 437.
——Wire rope cables, Pointers on the care of (H. C. Charles), 588.
——Wire rope research to continue, Conference recommends, 537.
Rotors (see Coils also motor reconnection and repair).

S

Safety:
——Accident prevention and the plant engineer (editorial comment), 245.
——Accidents, More mechanical handling—fewer (editorial comment), 525.
——Bar to prevent damage from falling belts, Safety (W. T. Claytor), *264.
——Congress help you reduce accidents, Let the safety (editorial comment), 463.
——Electric drills insures safety of operator, Grounding (R. H. Kasper), 640.
——Electric station design, The incorporation of safety in (V. R. Bacon), 373.
——Extinguishers from freezing, Keep fire, 560.
——Fire department a necessary adjunct to production, The industrial (T. J. O'Connor), *434.
——Fire, Protect production against (A. C. Hutson), *520.
——Fire protection equipment, How to inspect the (A. G. Smith), *151.
——"Fire tax," Yes, we all pay (editorial comment), 462.
——Flywheel, Determining safe speed of (W. F. Schaphorst), *370.
——Guard for power shearing machine (P. J. Edmonds), *98.
——Guards to increase production, Design (editorial comment), 196.
——Leadership, Safety through (editorial comment), 579.
——Modernization, And Safety in (H. P. Osborne), *527.
——Power transmission, Safeguarding equipment for (William Staniar), *626.
——Power transmission, Safety code for mechanical, 314.
——Resuscitation by the prone pressure method, *375.
——Static electricity on belts, Research reduces fire hazards from, 238.
——Switches, Emergency inclosure for open knife (Charles A. Peterson), *263.

Salvage:
——Machinery, Concerning junked, used and rebuilt (George Rice), 537.
——Scrap pile, Pick the dollars out of your (editorial comment), 362.
——Storage must tie in with replacement program, Salvage and (Henry F. Scott), *143.
——Who should do the salvaging? (see Are you ready for the question).

Sellers, and service, Buyers (editorial comment), 422.
Shafting (see also Lineshafting).
——Power transmission through steel shafting (William Staniar), *301.
——Pulley securely on shafting, Plate to hold wood (Murray MacDonald), *263.
——Safeguarding equipment for power transmission (William Staniar), *626.
Speed Control (see Control).
Speed Reducers (see also Drives and power transmission mechanical).
——When to replace geared speed reducers, 128.
Service (see also Plant service).
——Buyers, sellers, and service (editorial comment), 422.

Signals:
——Communication within industrial plants (Frank E. Gooding), *510.
——Materials-handling systems, Auxiliary devices prove their usefulness in (J. C. Siegesmund), *565.
——Mechanical aids to systematized production (J. L. Cochran), *499.
——Siren, Reducing cost of operating (Frank Gillooly), 82.
——Whistle serves as code call, Electrically-controlled, 412.
——"You'll have to wait until Mr. Blank comes back to the office" (editorial comment), 578.

Soldering (see also Welding).
——Aluminum wire, Simple method of soldering (Philip N. Emigh), 365.
——Fluxes save maintenance time and labor, Correct solders and (James Silberstein), *379.
——Nichrome for low-resistance joints (Philip N. Emigh) 206, (N. A. Voss) 206.

S

Sprockets:
——When to replace chains and sprockets, *154.
Standards, Agreement between the American Standards Association and the Bureau of, 499.
Starters (see Control).
Steel industry, Severe service as exemplified in the, *274.
Stock:
——Spare-parts stocks are insurance against breakdowns (editorial comment), 196.
Storage:
——Rack for bar stock, How to make sectional, *638.
——Salvage and storage must tie in with the replacement program (Henry F. Scott), *143.
Substations:
——Maintenance for dependable operation, Automatic substations need systematic (G. F. Jones), *394.
Switches (see Control).

T

Testing and tests:
——Circuit, Use of lamp in fuse block to indicate short (James P. Marshall), 410.
——How to connect and use electrical testing instruments (E. S. Lincoln), *89, correction 214.
——Low voltage for testing, Emergency sources of (Chas. A. Peterson), *588.
——Meters with out checking connections, Testing (E. J. Elvish), *477.
——Power, Measuring three-phase (Earl R. Witzel), *584, (C. O. Von Dannenberg), *584.
——Radio waves search out insulation faults, *98.
——Transformer maintenance for continuity of service, First aids in (D. R. Dalzell), *458.
——Welded joints, Stethoscope test for, 587.

Tools and Accessories:
——Cables, Reel facilitates handling of heavy (Charles A. Peterson), *638.
——Crane hooks that facilitate handling of flat objects (R. M. Thomas), *640.
——Electric drills insures safety of operator, Grounding, (R. H. Kasper), 640.
——Electric tools, When to replace portable, *149.
——Ferrules for tools out of old fuses, Making R. M. Thomas), 169.
——Grinder for turning hard steel rollers, Improvised (Joseph M. Spitzer), 211.
——Horses, Welded angle iron carpenter, *411.
——Lathe lighting fixture, An improved (Charles A. Peterson), *12.
——Lighting system, Housekeeping tools and methods for the plant (Robert L. Zahour), *212.
——Mica undercutting tool, Details of simple (W. F. Burket), *168.
——Plan holder for the machine shop (G. A. Luers), *11.
——Recording system, A simple tool (M. C. Cockshott), 211.
——Voltage for operating single-phase motors, Choice of (R. F. Emerson, 645, (Edward A. Gibbs), 645, (C. L. Hartman), 645.

Tractors (see trucks).
Trade literature, 56, 107, 176, 224, 271, 338, 388, 430, 488, 553, 600, 656.
Trailers (see trucks).
Transformers:
——Current on single-phase transformers, Determining full-load (Charles F. Cameron), *411.
——Installation insures reliable service, Correct transformer (David R. Dalzell), *69.
——Maintenance for continuity of service, First aids in transformer (D. R. Dalzell), *458.
——Parts, Hints on ordering transformer renewal (D. R. Dalzell), 570.

Transmission (see Power transmission).
Trucks (see also Handling materials).
——Battery charging equipment for electric trucks and tractors (H. M. Martin), *191.
——Battery charging room for plant trucks (Chas. A. Peterson), *211.
——Life of hand lift trucks, 314.
——Lubrication puts trucks and trailers on the spot, Scheduled, *609.
——Materials Handling equipment a necessary service to production in the metal working industry, *65.
——Replacements for electrical industrial trucks (C. B. Crockett), *123.
——Tires deserves your support, Simplification of industrial truck (editorial comment), 363.
——When to replace storage battery trucks and tractors, *158.

U

Unemployment (see Employment).

*Indicates illustrated articles

V

Ventilation:
——Air conditioning, Industry will do more (editorial comment), 422.
——Bleacheries severe service is the rule, In (C. D. Blackwelder), *287.
——Chemical plant, Combating corrosion in a (Eric Jensen), 315.
——Chinaware factory furnishes examples of the ceramic industry's severe service problems, A (A. A. Wells), *311.
——Motors in heated buildings, Outside air for (W. T. Claytor, Jr.), *97.
——Screens to keep plant dust from drafting rooms, Muslin (G. A. Luers), 480.
——Shop ventilator made from truck fan, Emergency (Henry Simon), *97.
Voltage regulators (see Motor control).

W

Welding:
——Aluminum wire, Simple method of soldering (Philip N. Emigh), 365.
——Equipment and still expect good service, Why you cannot neglect (C. N. Schafer), *58.
——Generator? What changes are required with this (J. F. Lincoln), 206 (P. P. Scribante), 371.
——Maintenance welding or have it done by a contract shop, Shall we do our own (M. Hallen), *232.
——Nichrome for low-resistance joints, Soldering (A. N. Voss), 206, (Philip N. Emigh), 206.
——Pipe angles with a water mark, Laying off (W. I. G.), *97.
——Saves the day, *618.
——Solders and fluxes save maintenance time and labor, Correct (James Silberstein), *379.
——Steam pipe is arc-welded, World's largest, 79.
——Test for welded joints, Stethoscope, 587.
——Trained welders only, For properly (editorial comment), 463.
——Who shall do the welding? (see Are you ready for the question).
Windings (see Motor windings).
Wire rope (see Rope, and cables).

W

Wiring (see also Cables).
——Area of copper wire, Graphical method of finding (Chas. F. Cameron), *265.
——Cables in manholes, Horrible examples of how not to arrange, *526.
——Changes are necessary, Running distribution lines when frequent (J. Elmer Housley), 477, (A. C. Barker), 585.
——Conduit re-shaped in place for new construction, Installed (J. E. Beneze), *210.
——Distributing 45,000 kw. how it is done at the Canton plant of the Timken Roller Bearing Company (W. A. Beck), *604.
Woodworking plants maintain efficiency of equipment, How two, *296.

Y

Yards:
——Floodlighting can do, What, *623.
——Neat yards mark the modern mill (Donald A. Hampson), *73.

AUTHORS' INDEX

A

ACHEE, H. J. Exciter loses field magnetism, 84.
——Preventing brush marks on collector rings.
Allen, C. W. How organized inspection prevents motor trouble, *444.
Arnold, Paul W. Designing for protection reduces motor maintenance. *235.
Arnold, T. H. Adapting 220-volt compensator for 440-volt operation, *263.

B

BACON, V. R. The incorporation of safety in electric station design, 373.
Barker, A. C. Running distribution lines when frequent changes are necessary, 585.
——Should extra men be hired or work sublet? 418.
Beck, W. A. Co-ordinate the function of the electrical repair shop for replacement, *145.
——Distributing 45,0000 kw.—how it is done at the Canton plant of the Timken Roller Bearing Company, *604.
——Organization for plant operation and maintenance, *340.
Beneze, L. E. Installed conduit re-shaped in place for new construction, *210.
——Preventing breakage of lamps from vibration, 169.
Benton, H. W. Method of demagnetizing motor shafts, 480.
——Should the plant engineering department have the right to question orders? 592.
——What shall be the maintenance policy? 453.
——Who shall do the welding? 632.
Billings, A. W. K. Why does this hemp-cord copper cable break? 205.
Billman, George S. What shall be the maintenance policy? 401.
——Who shall do the cleaning? 591.
Blackwelder, C. D. In bleacheries severe service is the rule, *287.
Black, Hugh A. Operation of three generators in parallel gives trouble, 418.
Bourdo, Albert. Simple water rheostat for emergency service, 479.
Brewer, Allen F. Automatic lubrication takes its place in service to production, *215.
Bromley, Richard. Locating short-circuited coils in a.c. motors, 83.
Brooks, H. B. How to determine wire sizes for electro-magnets, 349.
Burket, W. F. Details of simple mica undercutting tool, *168.

C

CAMERON, CHAS. F. Determining full-load current on single-phase transformers, *410.
——Graphical method of finding area of copper wire, *265.
Carter, E. D. What is causing trouble with this commutator? 82.
Charles, H. C. Plant track crossings, 238.
——Pointers on the care of wire rope cables, 588.
Chatfield, G. P. Trouble with mica V-ring of commutator, 260.
Claytor, Jr., W. T. Method of installing ball bearings in vertical ceiling fans, *479.
——Outside air for motors in heated buildings, *97.
——Safety bar to prevent damage from falling belts, *264.
Cochran, J. L. Mechanical aids to systematized production, *499.
Cockshott, M. C. A simple tool recording system, 211.
——Should the plant engineering department have the right to question orders? 401.
——Supporting brick walls where holes are cut through, 646.
——What shall be the maintenance policy? 356.
——Who shall do the welding? 633.
Coon, L. B. Should the plant engineering department have the right to question orders? 452.
Crockett, C. B. Replacements for electrical industrial trucks, *123.

D

DALZELL, DAVID R. Correct transformer installation insures reliable service, *69.
——First aids in transformer maintenance for continuity of service, *458.
——Hints on ordering transformer renewal parts, 570.
Dittmar, Dr. M. A. Good plant housekeeping is essential to our business, *533.
Drake, C. W. Why it is advisable to check up on motor loads, *318.
Drake, Robert W. Constant-speed drives for long conveyor chains, *390.
——Variable-speed drives for long conveyor chains, *439.
——What shall be the maintenance policy? 356.

E

EDMONDS, P. J. Guard for power shearing machine, *98.
Elvish, E. J. Testing meter without checking connections, *477.
Emerson, Grady H. Eliminating trouble with relay plungers, 83.
——Hasty diagnosis of electrical trouble does not pay, 479.
——Inexpensive design changes are often helpful, 97.
——Unusual case of trouble with mine hoist motor, 168.
——What is the theory of this relay? 164.
Emerson, R. F. Choice of voltage for operating single-phase motors, 645.
——Operation of Selsyn motor, 84.
——Operating 60-cycle motor on 50-cycles, *647.
——Raising hot water with centrifugal pump, 82.
——Reducing speed of slipring motor, *370.
——What causes poor starting of this motor? *478.
——What is causing trouble with this commutator? 205.
——What is the best method of stopping this crane? *165.
Emigh, John. Locking floor button controls sawmill equipment, *639.
Emigh, Philip N. Preventing brush marks on collector rings, 81.
——Simple method of soldering aluminum wire, 365.
——Soldering nichrome for low-resistance joints, 206.

F

FERGUSON, WILLIAM B. Electrical modernization without production delay, *530.
——Synchronous motor causes line surge, *259.
Fisher, H. D. Paper-making imposes conditions of severe service, *326.
——Supporting brick walls where holes are cut through, *646.
——What shall be the maintenance policy? 456.
——Who shall do the welding? 633.
Franklin, B. A. Budgeting upkeep keeps down expenses, *622.

G

EORGE, WALTER C. What shall be the maintenance policy? 357.
Gibbs, Edward A. Choice of voltage for operating single-phase motors, 645.
——What is causing trouble with this commutator, 82.
Gibson, F. M. The plant engineer's forum *6, *74, *166, *194, *252, *306.
Gillooly, Frank. Reducing cost of operating siren, 82.
Gooding, Frank E. Communication within industrial plants, 510.
Greenberg, Elbert E. Reducing maintenance cost on portable instruments, *169.
Guildford, R. P. Operating 60-cycle motor on 50-cycles, 647.

H

HALLEN, M. Shall we do our own maintenance welding or have it done by a contract shop, *232.
Hamilton, K. D. Checking the distribution of purchased power, *199.
——What shall be the maintenance policy? 457.
Hampson, Donald A. Neat yards mark the modern mill, *73.
——Uses for a disk grinder in the repair shop, 365.
Hansen, Frank A. Economic aspects involved in high-lighting industry, *561.
——High-lighting industry with 54.3 foot-candle intensity, *495.
Hartman, Fred. Trouble encountered in placing new commutator in service, 567.
Hartman, L. C. Choice of voltage for operating single-phase motors, 645.
Hoke, R. K. Cable extension for industrial electric locomotives, *11.
——Surge ring failure due to starting current inrush, 210.
Holston, Jas. B. Across-the-line motors, a discussion of their characteristics and use, *99.
——What causes poor starting of this motor? 645.
Hopkins, J. R. Linestart motors require wider pulleys and wider belts, 372.
——Maintenance and inspection of leather belts, *447.
Hornberger, L. B. Systematic inspection, maintenance, and lubrication, *156.
Housley, Elmer. Running distribution lines when frequent changes are necessary, 477.
——Should the plant engineering department have the right to question orders? 452.
——Who shall do the oiling? 630.
Hubbard, Charles L. A Dollar Twenty-Seven per Person per Year for Drinking Water, *76.
Hutson, A. C. Protect production against fire, *520.

J

JACKSON, J. A. Electric limit switches—their care and use, *358.
James, H. D. Features that distinguish alternating-current magnets, *467.
——Starters and controllers for electric motors, *228.
——Series-parallel and other methods of controlling motor speed, *568.
——Two methods of adjusting motor speeds, *366.
——What goes on inside the d.c. electro-magnet when operating contactors and similar equipment, *94.
Jensen, Eric. Combating corrosion in a chemical plant, *315.
Johnson, C. A. Adapting auto-starters to changed conditions, *580.

*Indicates illustrated articles

J

——Adapting auto-starters to changed conditions, *641.
Jones, G. F. Automatic substations need systematic maintenance for dependable operation, *394.

K

KAELIN, HENRY F. Troubles met in changing speed of single-phase motor, *364.
Kasper, R. H. Grounding electric drills insures safety of operators, 640.
——Replacing endless belts, 588.
——Sealing plastered walls against moisture, 584.
——Should the plant engineering department have the right to question orders? 634.
Kaufman, Robert. Hard facts about surfacing concrete floors, *61.
Keefer, T. A. What shall be the maintenance policy? 355.
Kramer, M. B. Who shall do the cleaning? 451.
——Who shall do the oiling? 631.
Krause, F. J. H. Method of cleaning busbars, 585.

L

LAABS H. E. Reducing speed of slipring motor, 370.
Lieber, G. R. Operation of three generators in parallel gives trouble, 418.
Lincoln, E. S. How to connect and use electrical testing instruments, *89. Correction 214.
Lincoln, J. F. What changes are required with this generator? 206.
Looser, J. C. Who shall do the cleaning? 592.
Luers, G. A. Handy plan holder for the machine shop, *11.
——Muslin screens to keep plant dust from drafting rooms, 480.

M

MacDONALD, MURRAY. Plate to hold wood pulley securely on shafting, *263.
McBrayer, W. R. What is the best method of stopping this crane? *164.
McFalls, E. C. Hard facts about surfacing concrete floors, *61.
McLaughlin, J. J. Defective units in the lighting system should be replaced at once, *116.
Maloney, T. J. Obtain more light by using proper colors for industrial interiors, *571.
Marshall, James P. Simple method of tightening expansion shields, 263.
——Use of lamp in fuse block to indicate short circuit, 410.
Martin, H. M. Battery charging equipment for trucks and tractors, *190.
Moore, Roy C. Measuring belt tension, 647.
Morrow, L. C. A practical-ideal organization for plant engineering, *504.
Murphy, R. E. What meter constant with odd-size paper? 84.
Myers, Harry C. Method of heating oil pipe line, 259.
Myers, H. M. Flexibility and ease of operation are obtained by modern controls, *420.

O

O'CONNOR, T. J. The industrial fire department—a necessary adjunct to production, *434.
Osborne, H. P. And safety in modernization, *527.

P

PACE, R. L. Locating short-circuited coils in a.c. motors, 83.
Pendergrass, Sr., W. H. What shall be the maintenance policy? 401.
Perrill, Dale M. It pays to know wire rope before ordering, *377.
Peterson, Charles A. Battery charging room for plant trucks, *211.
——Emergency inclosures for open knife switches, *263.
——Emergency sources of low voltage for testing, *588.
——How to keep unused paint, 204.
——Improved lathe lighting fixture, *12.
——Reel facilitates handling heavy cables, *638.
Peterson, M. Who shall do the cleaning? 634.
——Who shall do the welding? 591.
Petrowsky, John P. High-frequency power simplifies the motor application problem, *7.
Phillips, Marin. Who shall do the cleaning? 451.

P

——Who shall do the oiling? 631.
Proudfoot, C. S. The value of efficient service departments to the general manager, 393.

R

RICE, GEORGE. Concerning junked, used and rebuilt machinery, 537.
——New versus old machinery, 582.
Roe, A. C. Changing a twelve-pole motor to eight poles, *639.
——Chord factor of concentric winding, 49.
——Layer-wound pulled coils for partly-closed-slot machines, *207.
——Meaning of terms used in calculating motor windings, *371.
——Modernizing old motor windings, *538.
——Modernizing old motor windings—how to replace an old bar and end connector winding by the diamond two-layer type, *635.
——Replacing an old involute winding by the diamond two-layer type, *407.
——Replacing an old shove-through winding by the threaded-in type, *125.
——Replacing obsolete dropped-bottom-coil coils with the two-coil-per-slot pulled type, *261.
Rogers, R. H. What multi-speed motors offer to industry, *611.
——What synchronous motors offer to industry, *575.
Rooney, F. H. What is the best method of stopping this crane? 206.
Ross, W. G. How we are organized for maintenance and plant housekeeping, *178.
Rothschild, K. D. It pays to know your wire rope before ordering (a discussion), 437.

S

SACCO, E. J. Shifting brushes corrected instability of d.c. motor, 211.
Sawtelle, E. S. Plaster cast helps to visualize gear tooth wear, *168.
Schafer, C. N. Why you cannot neglect arc-welding equipment and still expect good service, *58.
Schaphorst, W. F. Can formation of static on belts be prevented? 83.
——Determining safe speed of flywheel, *370.
——Emergency method of bending pipes and tubes, 586.
Schoenberger, John H. Frame for Holding Small A.C. Stators While Rewinding, *412.
Schultz, H. L. Should the plant engineering department have the right to question orders? 399.
——Who shall do the oiling? 630.
Scott, Henry F. Salvage and storage must tie in with the replacement program, *143.
Scribante, P. P. What changes are required with this generator? 371.
Sheeler, Roy C. Fighting rust and corrosion with better painting methods, *182.
——How can better painting results be obtained? 49.
——How to keep unused paint, 419.
——Spend for replacement what you save by scheduled painting of structural parts and buildings, *129.
——The place of pyroxylin finishes in maintenance painting, *351.
Siegesmund, J. C. Auxiliary devices prove their usefulness in materials-handling system, *565.
Silberstein, James. Correct solders and fluxes save maintenance time and labor, *379.
Simon, Henry. Emergency shop ventilator made from truck fan, *97.
——How to make sectional rack for bar stock, *638.
Smith, A. G. How to inspect the fire protection equipment, *151.
Smith, E. D. National Cash Register organization for plant engineering, *464.
Smith, E. J. How a plant engineering department reduced the cost of gas 16 per cent, electricity 35 per cent, water 43 per cent, *247.
Smythe, H. V. Sealing plastered walls against moisture, 584.
Sooy, W. E. How should this lineshaft be driven? 646.
Spitzer, Joseph M. Improvised grinder for turning hard steel rollers, 211.
Stafford, H. E. It takes us three days to determine yearly costs, *413.
——Putting maintenance and inspection on a schedule basis, *140.
——Should the plant engineering department have the right to question orders? 400.

S

——What shall be the maintenance policy? 454.
——Who shall do the cleaning? 633.
Staniar, William. Lubrication of power transmission equipment, *556.
——Power transmission by leather belting, *85.
——Power transmission by short-center belt drives, *239.
——Power transmission through chains, *471.
——Power transmission through friction clutches, *402.
——Power transmission through speed reducers and variable speed units, *515.
——Power transmission through steel shafting, *301.
——Safeguarding equipment for power transmission, *626.
——Transmission of power by fabric-base belts, *133.
——Transmission of power to the driven machine, *2.
——Types of bearings used in transmission of power, *344.
——Types of pulleys used in transmission of power, *239.
Stearns, S. W. What is the best method of stopping this crane? 419.
Sterrett, Elton. Reducing the light bill, 12.
Sutherland, W. F. Bearing currents caused by solenoid shaft oscillator, *586.

T

THOMAS, R. M. Crane hooks that facilitate handling flat objects, *640.
——Making ferrules for tools out of old fuses, 169.
——Repairing cast iron pulley with broken rim, 411.
Thompson, Allison J. Vibration and its effects on lamp filaments, 416.

V

VAN BIBBER, P. T. Automatic motor speed variation during cutting operations, *251.
Von Dannenberg, C. O. Effects of induction voltage regulators, *164.
——Measuring three-phase power, *584.
——Method of calculating torque, 81.
——Operation of Selsyn motor, 371.
——Reducing speed of slipring motor, 371.
——Synchronous motor causes line surge, 259.
Voss, A. N. Soldering nichrome for low-resistance joints, 206.

W

WADE, J. M. Flexibility and ease of operation are obtained by modern controls, *420.
Wagner, Carl A. Easy method of stripping stators and armatures, 480.
——Method of filling holes in laminations, 81.
——Should extra men be hired or work sublet? 418.
Wallis, Roy C. Modern drives and materials-handling equipment mean low power consumption in this paving-brick plant, *490.
Warner, W. E. Practical tips on lubrication of equipment, 411.
Warrick, Woodward. Limitations of roller chain drives, *254.
Wells, A. A. A chinaware factory furnishes examples of the ceramic industry's severe service problems, *311.
Whitely, F. When supply lines go hay wire, 480.
Wikle, H. W. Automatic control for board tipple, *364.
Wilcox, C. C. What shall be the maintenance policy? 455.
Willard, F. H. What causes these belts to wabble? 83.
Williamson, G. Using balancer set to make three-wire system, *204.
Windle, A. E. Who shall do the welding? 590.
Witzel, Earl R. Measuring three-phase power, *584.
——Will new brush-holders keep these machines from sparking? 260.
Wolff, S. S. Trouble with mica V-ring of commutator, 260.
Wood, Fred C. Anchor bolt that saves time in setting machines, *264.
Wynhoff, J. J. How should this lineshaft be driven? 646.

Z

ZAHOUR, ROBERT L. Housekeeping tools and methods for the plant lighting system, *212.

*Indicates illustrated articles